


MCP25 Breakout Board

The MCP 25 Way breakout board (V2.1) has many uses including for CNC retrofitting / robot control. It allows you to wire to the parallel port / LPT port using screw terminals, this makes wiring limit / sensing switches to you CNC machine a breeze.

All connected printer I/O lines have screw terminal connector. It is very easy to wire limit / control switches.



Wiring Diagram



 Warning: Maximum 5V input on the Input port. Exceeding these ratings WILL destroy your PC or the printer port / interface card.